



197 State Route 18, Suite 3000 S. East Brunswick, New Jersey 08819
www.MechanicalinsulatorsLMCT.com

Pete Ielmini, *Executive Director* 732-210-7084 **Gina Walsh**, *Deputy Director* 314-683-6136

The following pages will outline a case study, which shows the benefits in energy and cost savings of properly installed mechanical insulation.

Insulation is a proven means for conserving energy, reducing greenhouse gas emissions, increasing process productivity, providing a safer and more productive work environment, controlling condensation (which can lead to mold growth), supporting sustainable design technology and a host of other benefits.

Mechanical insulation does all of this, while providing a return on investment (ROI) rate, which is seldom rivaled. Despite the proven ROI, insulation is often overlooked and its benefits undervalued. Insulation is truly the lost or forgotten technology. Can you think of a more important time than now to think about how insulation can help you?

An insulation system is a technology, which needs to be engineered and maintained throughout the entire process. Several studies have estimated roughly 10 to 30 percent of all installed insulation is now missing or damaged.

The practice of not replacing or maintaining an insulation system in a timely and correct manner reduces the full benefits of insulation, and in return, decreases the ROI. In many cases, significant other issues - such as excessive energy loss, corrosion under insulation (CUI), mold development, increased cost of operations and reduced process productivity or efficiency - develop.

You can learn more on www.MechanicalInsulatorsLMCT.com, where additional case studies can be viewed.

Please do not hesitate to contact me should you have any additional questions.
Thank you,

Peter Ielimi

Executive Director
Mechanical Insulators Labor Management Cooperative Trust

SALAMANDER INSPECTIONS LTD

Mechanical Insulation Energy Audits


Energy Audit

Eagle Park

777 Jones Street, Qualicum Beach

British Columbia

V9K 1R5



Executive Summary

Eagle Park is located at 777 Jones Street, Qualicum Beach, British Columbia. The care home is a multi level healthcare facility operated by Island Health Authority. For this report our inspection was for this buildings mechanical room and fan rooms only.

Salamander Inspections performed an energy audit of the insulation systems within the main Boiler Room and Fan Rooms. The purpose of the audit was to determine the current state of mechanical insulation applied to the systems.

Our findings indicate that there are opportunities to improve the mechanical insulation systems in a cost effective manner. The benefits are itemized below. Any deviation from following the Best Practices Guideline¹ developed by the North American Insulation Institute will reduce the potential savings and benefits. For example, we know that the elimination of canvas jacket can shorten the lifespan of fiberglass with an ASJ finish because of the lack of a protective cladding system. We also recommend using removable insulating pads where necessary or required for maintenance to ensure that the insulation systems remain intact for as long as possible.

Undertaking the projects we have identified in our review will yield:

- 1) Annual reduction of heat loss - **78 Gj** and a **ROI of 3 years**
- 2) Annual cost savings derived through properly insulated piping - **\$ 1150.50**
- 3) Potential savings on maintenance costs for equipment
- 4) Elimination of personal protection hazards

¹ Refer to <http://insulationinstitute.org/tools-resources/resource-library/codes-standards/> for more information in mechanical insulation systems.

Table of Contents

Executive Summary	i
About Salamander Inspections and the FLIR Thermographic Camera	2
Methodology	3
Study Findings	3
<i>Mechanical Room.....</i>	<i>3-9</i>
<i>Fan Rooms</i>	<i>9-12</i>
<i>Energy Calculations</i>	<i>13</i>
<i>Insulation Materials.....</i>	<i>14-15</i>
Recommendations and Conclusion.....	15
Disclosure.....	15
Limitations.....	15
Disclaimer.....	15
Signatures.....	16

Introduction

Mr. Kevin Ramlu, Energy Specialist for Island Health retained Salamander Inspections Ltd. to complete a review of mechanical insulation systems applied to the heating systems at Eagle Park Health Care Facility located in Qualicum Beach, British Columbia. The goal of the assessment is to find energy savings for the hospital.

About Salamander Inspections and the FLIR Thermographic Camera

Salamander Inspections Ltd. is a third party inspection service providing energy audits for mechanical systems in the Commercial/Institutional sector. We are utilizing a state of the art FLIR thermographic camera to provide us with accurate measurements and photographs of heat loss and gain on mechanical systems within the scope of work determined by our clients.

This heating plate exchanger, as photographed by the FLIR camera uses sensors built within the camera to show the heat radiating from the valve. The brighter the color the hotter the temperature of the object. The camera must be set up to filter out the ambient heat from surrounding objects to ensure that the temperatures are accurate. The camera then takes a thermal image as well as a digital picture for reference.




Figure 1 This is an infrared photo of the heat exchanger showing the areas with where large temperature differences create high rates of heat transfer.



Figure 2 This photo shows the same plate heat exchanger.

Methodology

The audit was performed by systematically inspecting the condition of all mechanical systems within the scope of work. The type of system, condition, temperature and footage was recorded and used to determine outcomes that will be beneficial to the operation of the building. The areas targeted within the scope of work have been checked using a FLIR digital thermal imaging camera which shows clearly problem areas that may not be seen with the naked eye. High rates of heat transfer are indicated in areas where there are large colour differences between the background elements within the area.

After identifying the problem areas with an infrared camera, we then completed simulations of different mechanical insulation systems. In this way, we were able to develop a cost versus benefit model for different insulation systems

Study Findings

Boiler Room

In general, workmanship on the **new insulation systems** is very good but there were some deficiencies if we compare the systems to the standards established in Best Practices Guideline² developed the North American Insulation Institute. For instance, valves, pumps, flanges and or fittings **should have been insulated at the time of retro fit**. However, we note that some specifications expressly omit this requirement thereby increasing operating costs for the owner. We are continuing our efforts to reach out to the engineering community to get elements such as these changed in specifications.

We have assessed the boiler room and found that the insulation applied to the older existing mechanical systems is in generally good condition. We noted that the remaining insulation before the retro fit took place is 1 inch thick (25mm). Current best practices and ASHRAE 90.1 (2010) requires that the insulation applied to heating systems be 1 ½ inch thick (40mm). The new insulation that has been applied on the upgraded mechanical heating systems follows ASHRAE 90.1 but the installers (company) did not completely insulate the systems leaving opportunities to save energy and lower GHG output.

There are some instances where pumps, valves and piping have no insulation applied and therefore, there is an opportunity to reduce operation costs. During the course of this inspection we counted at least (13) valves, (2) strainers, (8) pumps that should be insulated.

² Refer to <http://insulationinstitute.org/tools-resources/resource-library/codes-standards/> for more information in mechanical insulation systems.

Sample photos are provided below showing various components of the mechanical systems where upgrading the mechanical insulation will reduce operating costs by reducing energy consumption and extending the service life of equipment and also improve personnel safety (Figures 3 to 37).



Figure 3 This thermographic image of an exposed motorized heating pump at 58° C or 136° F.



Figure 4 This is a conventional photo of the same pump. There is also an exposed strainer and union.




Figure 5 This Thermographic image of HWR supply and return with exposed valves and Victaulic fittings.



Figure 6 This conventional photo shows the same valves and exposed Victaulic fittings. This work has been recently done and these valves and fittings should have been insulated.



Figure 7 This is a thermographic image of two motorized heating pumps at 75° C or 167° F.



Figure 8 This is a conventional photo of the two heating pumps. These pumps could have removable pads made and installed. The pads are re-useable for maintenance purposes.



Figure 9 This is a thermographic image of a Victaulic strainer/drain at 70.2° C or 158°F. There is a risk to personnel where temperatures exceed 65 ° C.



Figure 10 This is the conventional image of the same bare strainer/drain in the boiler room. Of note is the motorized pump with the Styrofoam packing around it acting as insulation. Maintenance personnel recognize the importance of the pump being insulated.




Figure 11 Thermographic image of recently done work showing inadequate insulation at the elbow and hot spots in various areas.



Figure12 This is a conventional image of the same valve and elbow. The thermal image shows the lack of insulation in some areas which is invisible to the naked eye.



Figure 13 This thermographic image is of bare flange to hot water tanks.



Figure 14 conventional image of the same flange.



Figure 15 Conventional image of a motorized valve to the hot water tanks.



Figure 16 Conventional image of the same motorized valve.



Figure 17 Thermographic image of a by-pass on the back of the boiler.



Figure 18 Conventional image of the same by-pass. Note the other bare piping/unions and strainer protruding through the insulation. Each object is a source of heat loss.



Figure 19 Thermographic image of motorized valve at 61° C or 141° F.



Figure 20 Conventional picture of the same motorized valve.



Figure 21 Thermographic image of a bare flange tying into existing systems.



Figure 22 Conventional image of the same flange.



Figure 23 Thermographic image of control valves at the back of the boilers.



Figure 24 conventional image of the same control valves.



Figure 25 Thermographic image of the supply and return lines at the back of the boiler.



Figure 26 Conventional image of the same lines.



Figure 27 Thermographic image of a gate valve and piping at back of the boiler.



Figure 28 Conventional image of the same gate valve and piping.




Figure 29 Thermographic image of piping at back of boiler.



Figure 30 Conventional image of the same pipe.

Fan Rooms

The inspection of all of the fan room mechanical areas has revealed that the insulation was generally applied correctly. The issue remains however that there are (6) fan rooms where insulation is missing on some of the piping supplying heating water to the coils. Portions of the mechanical system have been refurbished to improve the efficiency. When the contractors retrofitted the mechanical systems they should have also correctly installed the mechanical insulation systems. Unfortunately, the contractor missed this opportunity. Failure to complete the insulation system has left opportunities to improve or upgrade the insulation and receive benefits to the cost of operation. There is approximately (27) meters of insulation missing from the mechanical within these mechanical rooms. (figures 31– 46)



Figure 31 Thermographic image of bare motorized Tee at AHU -1.



Figure 32 Thermographic image of the same bare motorized Tee.



Figure 33 Thermographic image of bare motorized heating pump P-1.



Figure 34 Conventional image of the same motorized heating pump.



Figure 35 Thermographic image of bare heating supply to coils.



Figure 36 Conventional image of bare small bore heating supply to coils.



Figure 37 Thermographic image of bare heating supply to coils.



Figure 38 Conventional image of bare small bore heating supply and return to coils.




Figure 39 Thermographic image of bare copper heating supply to coils.



Figure 40 Conventional image of bare small bore heating supply and return to coils.



Figure 41 Thermographic image of bare three way small bore supply and return.



Figure 42 Conventional image of the same small bore supply and return lines.



Figure 43 Thermographic image of bare three way small bore supply and return.



Figure 44 Conventional image of the same small bore supply and return lines.




Figure 45 Thermographic image of bare small bore supply and return and motorized pump.



Figure 46 Conventional image of the same small bore supply and return lines and motorized pump.

Personnel Protection

It is also important to recognize the hazards that hot exposed surfaces present to personnel. The boiler rooms and fan rooms generally are tightly packed with equipment and piping systems operating at temperatures of nearly 62°C. (People experience burns at temperatures above 65°C). Un-insulated or exposed surfaces at these high temperatures are to be considered a serious risk for staff and personnel. Properly insulated systems and equipment eliminate the possibility of individuals coming into contact with these hot surfaces and will prevent accidental burns. This is an important life safety and financial consideration.

Energy Calculations

Table 1.0 below summarizes our energy calculation. We completed our calculations using a program developed by the Insulation Institute (see insulationinstitute.org) called 3E Plus. We can make our detailed calculations available upon request.

The summary provides an aggregate heat loss rate for...

Table 1.0 Energy and Financial Savings

Hours of Operation	KWh from Spreadsheet	Gigajoules Saved
8760	21644	78
	Cost of fuel	\$ 14.75
	total	\$1150.50

Table 2.0 Greenhouse Gas Emission Reduction

Greenhouse Gas	CO2	NOx
Total removed	3.9 tonnes	0.0 tonnes

Insulation Materials

Table 3.0 provides a list of materials needed to insulate areas noted during our inspection, these are used as input for the 3EPlus spreadsheet for heat loss calculations. The insulation costs are estimates only and should not be used as actual costs.

Table 3.0 Insulation Upgrade Pricing Summary

Pipe Sizes	Square footage or Lineal feet	Cost of Material
Tank Wrap		
5/8		
1/2	27 ft @ \$ 17.53	\$ 473.31
3/4	3 ft @ \$ 17.92	\$ 53.76
1 1/4	1 ft @ \$ 18.64	\$ 18.64
1 1/8		
1 1/2	46.04 ft @ \$	\$ 871.07
2	8 ft @ \$ 19.35	\$ 154.80
2 1/8		
2 1/2	16 ft @ \$ 20.19	\$ 323.04
2 5/8		
3	30.45 ft @ \$ 20.63	\$ 628.18
3 1/8		
4	11.64 ft @ \$ 21.88	\$ 254.68
5	7.12 ft @ \$ 23.00	\$ 163.76
6	1 ft @ \$ 24.14	\$ 24.14
7	7.62 ft @ \$ 25.12	\$ 191.41
8	1.75 ft @ \$ 26.59	\$ 46.53
10		
12		
14	8.54 ft @ \$ 33.87	\$ 289.24
Total		\$ 3,492.56

All materials noted in the above table are to be of a wall thickness of 1.5 inches or greater dependent upon temperature rating. The costs for insulation include PVC cladding, elbows and fittings. The cost of labor is also part of the lineal footage costs. Price also includes 5% for PST. We highly recommend that Island Health get three quotes to compare. This price is an estimate only and may not be considered an exact amount.

Recommendations and Conclusions

Our findings indicate that there are opportunities to improve the mechanical insulation systems in a cost effective manner. The benefits are itemized below. Any deviation from following the Best Practices Guideline³ developed by the North American Insulation Institute will reduce the potential savings and benefits. For example, we know that the elimination of canvas jacket can shorten the lifespan of fiberglass with an ASJ finish because of the lack of a protective cladding system. We also recommend using removable insulating pads where necessary or required for maintenance to ensure that the insulation systems remain intact for as long as possible.

If all areas are addressed, the benefits shall include:

- 1) Annual reduction of heat loss - **682 GJ**
- 2) Annual cost savings derived through properly insulated piping - **\$10,059**
- 3) Potential savings on maintenance costs for equipment
- 4) Elimination of personal protection hazards Disclosure
- 5) We have no relevant financial or non-financial relationships to disclose.

³ Ibid.

Limitations

We have used information provided to us from various sources but information such as operational heating cycles and cooling cycles are based on conversations with maintenance personnel.

Disclaimer

Results stated in this report are estimated and based upon the data supplied or determined during the audit process. Only the previously agreed to areas have been included in this report. These results are not covered by warranty nor are they guaranteed. The results are intended to portray a reasonable estimate of potential energy savings and emissions reduction with the use of an upgraded and maintained insulation system.

Please contact the undersigned should you have questions about this report.

Best regards,

Report prepared by:
Salamander Inspections



Bob Barter (Project Coordinator)

Reviewed by:
Besant and Associates Engineers Ltd.



Jeff Besant, MBA, P.Eng.

