



197 State Route 18, Suite 3000 S. East Brunswick, New Jersey 08819
www.MechanicalinsulatorsLMCT.com

Pete Ielmini, *Executive Director* 732-210-7084 **Gina Walsh**, *Deputy Director* 314-683-6136

The following pages will outline a case study, which shows the benefits in energy and cost savings of properly installed mechanical insulation.

Insulation is a proven means for conserving energy, reducing greenhouse gas emissions, increasing process productivity, providing a safer and more productive work environment, controlling condensation (which can lead to mold growth), supporting sustainable design technology and a host of other benefits.

Mechanical insulation does all of this, while providing a return on investment (ROI) rate, which is seldom rivaled. Despite the proven ROI, insulation is often overlooked and its benefits undervalued. Insulation is truly the lost or forgotten technology. Can you think of a more important time than now to think about how insulation can help you?

An insulation system is a technology, which needs to be engineered and maintained throughout the entire process. Several studies have estimated roughly 10 to 30 percent of all installed insulation is now missing or damaged.

The practice of not replacing or maintaining an insulation system in a timely and correct manner reduces the full benefits of insulation, and in return, decreases the ROI. In many cases, significant other issues - such as excessive energy loss, corrosion under insulation (CUI), mold development, increased cost of operations and reduced process productivity or efficiency - develop.

You can learn more on www.MechanicalInsulatorsLMCT.com, where additional case studies can be viewed.

Please do not hesitate to contact me should you have any additional questions.
Thank you,

Peter Ielimi

Executive Director
Mechanical Insulators Labor Management Cooperative Trust

SALAMANDER INSPECTIONS LTD

Mechanical Insulation Energy Audits


Energy Audit

Tofino General Hospital

261 Neill Street, Tofino

British Columbia

VOR 2Z0



Executive Summary

Tofino General Hospital is located at 261 Neill Street Tofino, British Columbia. The hospital contains all medical services for the community of Tofino. For this report our inspection was for this buildings mechanical room only.

Salamander Inspections performed an energy audit of the insulation systems within the main Boiler Room. The purpose of the audit was to determine the current state of mechanical insulation applied to the systems.

Our findings indicate that there are opportunities to improve the mechanical insulation systems in a cost effective manner. The benefits are itemized below. Any deviation from following the Best Practices Guideline¹ developed by the North American Insulation Institute will reduce the potential savings and benefits. For example, we know that the elimination of canvas jacket can shorten the lifespan of fiberglass with an ASJ finish because of the lack of a protective cladding system. We also recommend using removable insulating pads where necessary or required for maintenance to ensure that the insulation systems remain intact for as long as possible.

Undertaking the projects we have identified in our review will yield:

- 1) Annual reduction of heat loss - **32.4 GJ** and a **ROI of 2.7 years**
- 2) Annual cost savings derived through properly insulated piping - **\$ 873.50**
- 3) Potential savings on maintenance costs for equipment
- 4) Elimination of personal protection hazards

¹ Refer to <http://insulationinstitute.org/tools-resources/resource-library/codes-standards/> for more information in mechanical insulation systems.

Table of Contents

Executive Summary	i
About Salamander Inspections and the FLIR Thermographic Camera	2
Methodology	3
Study Findings	3
<i>Mechanical Room.....</i>	<i>3-8</i>
<i>Energy Calculations</i>	<i>9</i>
<i>Insulation Materials.....</i>	<i>10</i>
Recommendations and Conclusion.....	11
Disclosure.....	12
Limitations.....	12
Disclaimer.....	12

Introduction

Mr. Kevin Ramlu, Energy Specialist for Island Health retained Salamander Inspections Ltd. to complete a review of mechanical insulation systems applied to the heating systems at Tofino General Hospital located in Tofino, British Columbia. The goal of the assessment is to find energy savings for the hospital.

About Salamander Inspections and the FLIR Thermographic Camera

Salamander Inspections Ltd. is a third party inspection service providing energy audits for mechanical systems in the Commercial/Institutional sector. We are utilizing a state of the art FLIR thermographic camera to provide us with accurate measurements and photographs of heat loss and gain on mechanical systems within the scope of work determined by our clients.

This heating plate exchanger, as photographed by the FLIR camera uses sensors built within the camera to show the heat radiating from the valve. The brighter the color the hotter the temperature of the object. The camera must be set up to filter out the ambient heat from surrounding objects to ensure that the temperatures are accurate. The camera then takes a thermal image as well as a digital picture for reference.




Figure 1 This is an infrared photo of the heat exchanger showing the areas with where large temperature differences create high rates of heat transfer.



Figure 2 This photo shows the same plate heat exchanger.

Methodology

The audit was performed by systematically inspecting the condition of all mechanical systems within the scope of work. The type of system, condition, temperature and footage was recorded and used to determine outcomes that will be beneficial to the operation of the building. The areas targeted within the scope of work have been checked using a FLIR digital thermal imaging camera which shows clearly problem areas that may not be seen with the naked eye. High rates of heat transfer are indicated in areas where there are large colour differences between the background elements within the area.

After identifying the problem areas with an infrared camera, we then completed simulations of different mechanical insulation systems. In this way, we were able to develop a cost versus benefit model for different insulation systems

Study Findings

Boiler Room

In general, workmanship on the existing insulation systems is fair but there were some deficiencies if we compare the systems to the standards established in Best Practices Guideline² developed the North American Insulation Institute. For instance, valves, pumps, flanges and or fittings should have been insulated at the time of construction. However, we note that some specifications expressly omit this requirement thereby increasing operating costs for the owner. We are continuing our efforts to reach out to the engineering community to get elements such as these changed in specifications.

We have assessed the boiler room and found that the insulation applied to the mechanical systems is in generally fair condition. We noted that the existing insulation is 1 inch thick (25mm). Current best practices and ASHRAE 90.1 (2010) requires that the insulation applied to heating systems be 1½ inch thick (40) mm. The insulation that is applied is showing it's age and there are obvious signs of maintenance where materials have been removed and not replaced.

However, there are some instances where pumps, valves and piping have no insulation applied and therefore, there is an opportunity to reduce operation costs. During the course of this inspection we counted at least (16) small bore valves, (5) strainers, (10) pumps that should be insulated. In addition, there are other areas where there would be opportunities to install or upgrade the mechanical insulation systems.

² Refer to <http://insulationinstitute.org/tools-resources/resource-library/codes-standards/> for more information in mechanical insulation systems.

Sample photos are provided below showing various components of the mechanical systems where upgrading the mechanical insulation will reduce operating costs by reducing energy consumption and extending the service life of equipment and also improve personnel safety (Figures 3 to 28).



Figure 3 This thermographic image of copper piping within a stainless cabinet.



Figure 4 This is a conventional photo of the same piping.



Figure 5 This Thermographic image of the copper piping within the cabinet and leaving the cabinet.



Figure 6 This conventional photo shows the same piping and also shows the deterioration of the mechanical insulation and fittings.



Figure 7 This is a thermographic image of a bare 1 1/4 pipe above the boilers.



Figure 8 This is a conventional photo of the same piping.



Figure 9 This is a thermographic image of a bare 2 inch line high above the boilers.



Figure 10 This is the conventional image of the same line. (just below the blue colored line)



Figure 11 This thermographic image is of bare 1 1/4 iron pipe and associated fittings and valves.



Figure 12 This is a conventional image of the same group of pipe, fittings and valves.



Figure 13 This thermographic image is of a bare control valve.



Figure 14 This is a conventional image of the same valve.



Figure 15 This thermographic image is of a motorized pump from the domestic hot water tank.



Figure 16 This conventional image is of the same circulation pump.



Figure 17 Thermographic image of a bare circulation pump and piping.



Figure 18 conventional image of the same pump and piping.



Figure 19 Thermographic image of a bare Victaulic elbow and backflow preventer.



Figure 20 Conventional image of the same elbow and backflow preventer.



Figure 21 Thermographic image of a control valve, thermostat and elbow from the heating supply line.



Figure 22 Conventional image of the same control valve.



Figure 23 Thermographic image of motorized pump on heating system.



Figure 24 Conventional image of the same pump and associated flanges



Figure 25 Thermographic image of missing insulation on small bore heating supply.



Figure 26 Conventional image of the same piping with damaged and missing insulation.



Figure 27 Thermographic image of hanger supports without insulation behind plates.



Figure 28 Conventional picture of hanger support.

The inspection of all these mechanical areas has revealed that the insulation is generally applied correctly. The issue remains however that there are many areas where insulation has not been applied i.e.: pumps (heating) valves, piping and more. The level of finishing is inadequate in many of these areas where the installer stopped short of complete coverage of piping, valves and flanges. Failure to complete the insulation system has left many opportunities to improve or upgrade the insulation and receive benefits to the cost of operation.

Personnel Protection

It is also important to recognize the hazards that hot exposed surfaces present to personnel. The boiler rooms and fan rooms generally are tightly packed with equipment and piping systems operating at temperatures of nearly 77°C. (People experience burns at temperatures above 65°C). Un-insulated or exposed surfaces at these high temperatures are to be considered a serious risk for staff and personnel. Properly insulated systems and equipment eliminate the possibility of individuals coming into contact with these hot surfaces and will prevent accidental burns. This is an important life safety and financial consideration.

Energy Calculations

Table 1.0 below summarizes our energy calculation. We completed our calculations using a program developed by the Insulation Institute (see insulationinstitute.org) called 3E Plus. We can make our detailed calculations available upon request.

The summary provides an aggregate heat loss rate for...

Table 1.0 Energy and Financial Savings

Hours of Operation	KWh from Spreadsheet	Gigajoules Saved
8760	8,992.8	32.4
	Cost of fuel	\$26.96
	total	\$ 873.50

Table 2.0 Greenhouse Gas Emission Reduction

Greenhouse Gas	CO2	NOx
Total removed	1.6 tonnes	0.0 tonnes

Insulation Materials

Table 3.0 provides a list of materials needed to insulate areas noted during our inspection, these are used as input for the 3EPlus spreadsheet for heat loss calculations. The insulation costs are estimates only and should not be used as actual costs.

Table 3.0 Insulation Upgrade Pricing Summary

Pipe Sizes	Square footage or Lineal feet	Cost of Material
Tank Wrap		
5/8		
1/2		
3/4		
1 1/4	35 ft @ \$ 18.64	\$ 652.40
1 1/8		
1 1/2		
2	74 ft @ \$ 19.35	\$ 1,431.90
2 1/8		
2 1/2		
2 5/8		
3	5 ft @ \$20.63	\$ 103.15
3 1/8		
4		
5	10.5 ft @ \$ 23.00	\$241.50
6		
7		
8		
10		
12		
14		
Total		\$ 2,428.95

All materials noted in the above tables are to be of a wall thickness of 1.5 inches or greater dependent upon temperature rating. The costs for insulation include PVC cladding, elbows and fittings. The cost of labor is also part of the lineal footage costs. Price also includes 5% for PST. We highly recommend that Island Health get three quotes to compare. This price is an estimate only and may not be considered an exact amount.

Recommendations and Conclusions

Our findings indicate that there are opportunities to improve the mechanical insulation systems in a cost effective manner. The benefits are itemized below. Any deviation from following the Best Practices Guideline³ developed by the North American Insulation Institute will reduce the potential savings and benefits. For example, we know that the elimination of canvas jacket can shorten the lifespan of fiberglass with an ASJ finish because of the lack of a protective cladding system. We also recommend using removable insulating pads where necessary or required for maintenance to ensure that the insulation systems remain intact for as long as possible.

If all areas are addressed, the benefits shall include:

- 1) Annual reduction of heat loss - **32.4 GJ**
- 2) Annual cost savings derived through properly insulated piping - **\$ 873.50**
- 3) Potential savings on maintenance costs for equipment
- 4) Elimination of personal protection hazards Disclosure
- 5) We have no relevant financial or non-financial relationships to disclose.

³ Ibid.

Limitations

We have used information provided to us from various sources but information such as operational heating cycles and cooling cycles are based on conversations with maintenance personnel.

Disclaimer

Results stated in this report are estimated and based upon the data supplied or determined during the audit process. Only the previously agreed to areas have been included in this report. These results are not covered by warranty nor are they guaranteed. The results are intended to portray a reasonable estimate of potential energy savings and emissions reduction with the use of an upgraded and maintained insulation system.

Please contact the undersigned should you have questions about this report.

Best regards,

Report prepared by:
Salamander Inspections



Bob Barter (Project Coordinator)

Reviewed by:
Besant and Associates Engineers Ltd.



Jeff Besant, MBA, P.Eng.