

2021 Audi e-tron quattro

Weak Key Fob – Failure to Recognize



When e-tron quattro proximity Key Fob Batteries become weak the vehicle may have difficulty acknowledging its presence and not start.

Placing Fob in the designated area will aid in starting the vehicle.

The designated area in e-tron quattro is in the front cup holder in the center console.



Immediately replace the weak Key Fob Battery