




Firmware Changelog



V0.96 - 09-16-19

1. Improved Dimming and Color Mixing Capabilities
2. Improved Wireless Performance when dimming
3. Bug Fix – RDM fixes
4. Bug Fix – Eliminated lamps flashing at the 1 hour mark when on DMX
5. Bug Fix – Fixed lamp restart issues when crossfading from White light to a mixed RGB color
6. On DMX, Effects stop at 0% speed