


## Profile



©2010 National Coatings Corporation.  
All Rights Reserved.

# SEARS WAREHOUSE

*Size: 100,000 Square Feet*

*Location: Vernon, California*

## **Challenge** *Leaking & Corroding Metal Roof*

- Leaks at seams & fasteners.
- Mounting surface corrosion.
- Uncomfortable warehouse during summer.

## **Solution** *AcryShield® Restoration System*

- Rust-inhibitive primer system.
- Reinforced seams & fasteners.
- Reduced summertime surface temperatures by 50°F.

*Sears chose a Cool Roof restoration system to solve typical metal roof leak problems and to eliminate excess heat stress due to the intrinsic low heat release properties of bare metal and aluminum coated roofs.*

**NATIONAL  
COATINGS**

**COOL  
ROOF  
SYSTEMS®**

**NATIONAL**

**COATINGS**

1201 Calle Suerte, Camarillo, CA 93012

(800) 423-9557, Fax (800) 294-3866

[www.nationalcoatings.com](http://www.nationalcoatings.com), [info@nationalcoatings.com](mailto:info@nationalcoatings.com)